


IVITALENITAL OF

alphametals.

Jersey City, New Jersey 07304 Telephone 201-434-6778



SECTION I. GENERAL INFORMATION

PRODUCT NAME (NUMBER)

Solder Alloy 95 Sn/5 Sb

CHEMICAL FAMILY D.O.T. HAZARD CLASS Inorganic Metals. Not regulated.

SECTION II. HAZARDOUS INGREDIENTS

INGREDIENTS	CAS	WEIGHT	OSHA	ACGIH
	NUMBER	PERCENT	PEL	TLV
Tin	7 4 4 0 - 3 i - 5	9 5	•	2.0 mg/cum
Antimony	7 4 4 0 - 3 6 - 0	5		0.5 mg/cum

SECTION III. PHYSICAL DATA

(PUBLISHED OR ESTIMATED VALUES)

BOILING POINT Deg F.

NA

SPECIFIC GRAVITY

NA

(760 mm Hg)

NA

(H2O = 1)

VAPOR PRESSURE

% VOLATILE BY WEIGHT

NA

(mm Hg at 20 Deg. C.)

EVAPORATION RATE

NA

VAPOR DENSITY (AIR=1) SOLUBILITY IN WATER

NA

pΗ

APPEARANCE AND ODOR

Insoluble Silver-white metal, odorless.

NA

SECTION IV. FIRE AND EXPLOSION HAZARD DATA

ESTIMATED FLAMMABLE LIMITS (% By Volume in Air)

LEL:

NA

UEL:

NA

FLASH POINT Deg F.

NA

EXTINGUISHING MEDIA

NA

SPECIAL FIRE FIGHTING **PROCEDURES** Use NIOSH approved self-contained breathing apparatus and full protective clothing if

involved in a fire.

UNUSUAL FIRE AND EXPLOSION None.

HAZARD

NE - NOT ESTABLISHED


NL - NOT LISTED

UN - UNKNOWN



alphametals

600 Route 440 Jersey City, New Jersey 07304 Telephone 201-434-6778



Solder Alloy 95 Sn/5 Sb

SECTION V.(A) HEALTH HAZARD DATA

(Symptoms/Effects Of Overexposure)

TIN: Tin is relatively non-toxic, but may cause fever, nausea, stomach cramps or diarrhea. Dust or fume may cause irritation of the skin and mucous membranes. Stannosis, a benign pneumoconiosis may result from excessive tin exposure.

ANTIMONY: Liver and kidney abnormalities or pneumonitis may result from chronic antimony exposure. Some animal studies indicate that inhalation of antimony trioxide may pose an increased risk of lung cancer.

LISTED CARCINOGENS: None of the metal elements of this product are listed as carcinogenic by NTP, IARC, or OSHA.

MEDICAL CONDITIONS POSSIBLY AGGRAVATED: Diseases of the lung, kidney, liver and nervous system.

SECTION V.(B) HEALTH HAZARD DATA

(Emergency and First Aid Procedures)

INHALATION

Not likely to occur. If dust or vapor is present remove

individual from exposure. A NIOSH/MSHA approved respirator should be worn where airborne exposures may exceed permissable

air limits.

INGESTION

Not likely to occur. Tin is of a low order of toxicity because of poor absorption and rapid excretion of the metal from human tissue. Product contains 5 percent antimony. Consult Poison

Control Center for First Aid.

SKIN

CONTACT

After handling wash with soap and water.

EYE

Flush with water. Dust may cause irritation. If irritation

CONTACT persists get medical attention.

SECTION VI. REACTIVITY DATA

STABILITY

STABLE: X

UNSTABLE:

CONDITIONS

TO AVOID

INCOMPATABILITY

(Materials to Avoid)

Strong acids and strong bases.

HAZARDOUS

Antimony trioxide may be evolved at decomposition

NA

DECOMPOSITION PRODUCTS

temperature.

HAZARDOUS POLYMERIZATION

WILL OCCUR:

WILL NOT OCCUR;

•

CONDITIONS TO AVOID


NA



IVIAIEKIAL JAFEIT DAIA JAEEI

alphametals

600 Route 440 Jersey City, New Jersey 07304 Telephone 201-434-6778



04/01/99

828

Solder Alloy 95 Sn/5 Sb

SECTION VII. SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Product is solid metal.

WASTE DISPOSAL Scrap or waste may be recycled or collected for disposal.

Must be in accordance with Federal, State and Local Laws and Regulations

SECTION VIII. SPECIAL PROTECTION

RESPIRATORY

A NIOSH/MSHA approved dust/fume respirator should be worn where

the TLV may be exceeded.

EYEWEAR

Safety glasses and/or face protection is recommended for

exposures to dust, grinding or other operations generating

flying particles.

CLOTHING/

GLOVES

Protective gloves should be worn if skin contact is appreciable.

VENTILATION

Provide sufficient mechanical (general and/or local exhaust)

ventilation to maintain exposure below the TLV.

SECTION IX. SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Food and drink should not be consumed or tobacco products used, nor cosmetics applied in areas where metal may be used. Always wash after handling and before eating, drinking or smoking.

OTHER PRECAUTIONS:


Containers: Since empty containers may retain product residues (vapor, liquid, or solid) all labeled hazard precautions must be observed. FOR INDUSTRIAL USE ONLY. KEEP OUT OF REACH OF CHILDREN. DO NOT TAKE INTERNALLY.



IVIMICKIAL DAFETT DATA STICET

alphametals

600 Route 440 Jersey City, New Jersey 07304 Telephone 201-434-6778



Solder Alloy 95 Sn/5 Sb

SECTION X. ADDITIONAL INFORMATION

----- REGULATORY INFORMATION -----

Toxic Substance Control Act (TSCA) Status:

All ingredients of this product are listed on the TSCA inventory.

SARA TITLE III (Section 313):

Components present in this product at a level which could require reporting under the statute are:

Antimony

California State Proposition 65:

This product does not contain chemicals which the State of California has found to cause cancer, birth defects or other reproductive harm.

EMERGENCY TELEPHONE NUMBER

CHEMTREC

1-800-424-9300

DAY OR NIGHT

The information contained herein is based on data considered accurate and is offered at no charge. No warranty is expressed or implied regarding the accuracy of this data. Liability is expressly disclaimed for loss or injury arising out of use of this information or the use of any materials designated.